

# Edney Common Playground Inspection

12 Mar 2023 / Steve Maclean

Complete

Score	100%	Flagged items	0	Actions	0
-------	------	---------------	---	---------	---

Conducted on	12.03.2023 11:25 GMT
--------------	----------------------

Prepared by	Steve Maclean
-------------	---------------

Location	The Green Man, Edney Common, Chelmsford CM1 3QE, UK (51.713352, 0.385593)
----------	--

**Edney Common**

100%

**Are the gates working**

Yes

No padlock and chain



Photo 1

**Condition of roundabout**



Photo 2

**Condition of Thumper Tower**



Photo 3



Photo 4




Photo 5



Photo 6




Photo 7

**Condition of swings**



Photo 8



Photo 9



Photo 10

**Condition of seesaw**



Photo 11

**Condition of dome**



Photo 12

---

### Condition of multi square



Photo 13

---

### Condition of goal



Photo 14

---

## Any other notes

### Additional notes




Photo 15



Photo 16



Photo 17



Photo 18

## Appendix



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10





Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18